

## List of H<sub>2</sub>S caution signs - medium and high risk - Litvínov refinery



<i>item</i>	<i>operation</i>	<i>number</i>	<i>risk</i>
1.	PSP	13	HIGH
2.	STRUCTURE no. 1311	10	HIGH
3.	NRL	21	HIGH
4.	NRL	49	MEDIUM
5.	COMPRESSOR ST. PS5410	7	MEDIUM
6.	DISTILLATION "D"	12	MEDIUM
7.	RAFEX st. 4436	10	MEDIUM
8.	AVD	20	MEDIUM
9.	HYDROTREATMENT	34	HIGH
10.	HYDROTREATMENT	43	HIGH
11.	STRUCTURE "300"	30	HIGH
12.	STRUCTURE no. 3534	3	MEDIUM
13.	CLAUS	31	HIGH